MAJOR STRUCTURAL ENGINEERING PROJECTS

YEAR 1990 - 2004

17

51 Sakra Ave

Epoxy grouting & patch repair to Rc footing at

DESCRIPTION OF WORKS S/N PROJECTS Year 2004 Controlled demolition to RC wall at Block PB of Controlled demolition at Catholic High 1 Catholic High School School Repair to defective/spalling concrete surface Prepacked Grouting 2 for Column S15 (South/West face) at Hydrocracker West Rack Fin Fan Area at Shell Bukom Repair to defective pillars at TGU complex (S7 Prepacked Grouting Category civil works) at Shell Bukom Repair to defective concrete structure for Prepacked Grouting Switch-house 24B at Hydrocracker Plant (Part C - Repair works) at Shell Bukom Repair to defective concrete structure for Excavation, Erection of Temp Propping & switch-house 24B at Hydrocracker plant (Part Structural Investigation B - Excavation, Propping & investigation work) at Shell Bukom Proposed crack repair by cementitious grouting Crack repair by cementitious grouting at No. 2 Jalan Parisan 7 Repair to defective concrete structure for Repair to defective concrete structure for switch-house 24B at Hydrocracker plant (Part switch-house 24B at Hydrocracker plant A) at Shell Bukom (Part A) A & A works to existing timber roof trusses at A & A works to existing timber roof trusses 20 Mount Sinai lane, Singapore 277011 A&A to existing Holy Innocents' High School Post Tensioning Works 10 Investigation and Assessment of concrete Structural investigation structure at TGU at Shell Bukom RD107 Upgrading of Vehicular Bridges at 8 11 Post tensioning works Locations 12 Reconstruction of grout base for vessel E-Grouting to base 2201A & E-2201B at IPA plant at Shell Bukom 13 Repair to defective/spalling concrete surface at **Prepacked Grouting** CD 5 complex at Shell Bukom A&A to existing Holy Innocents' High School 14 Post Tensioning Works 15 Controlled demolition to RC beams at 20 Mt Controlled demolition Sinai Lane 16 Repair to defective Beam and Columns at CD5 **Prepacked Grouting** Complex (5 Quotations) at Shell Bukom

Epoxy grouting & Patch repair to Rc footing

<u>S/N</u>	<u>PROJECTS</u>	DESCRIPTION OF WORKS
18	Crack repair to Singapore Changi Airport - Cargo Stand Runway	Crack repair to Cargo Stand Runway
19	A&A works to Chen Su Lan Methodist Children's Home AT 202 Serangoon Garden Way	Post Tensioning Works
20	Beam Strengthening at Bishan Park Secondary School	Post tensioning work
21	Repair to water seepage at 2 sty staircase soffot & balcony entrance @ Watten View No 44	Repair to water seepage
22	Shell Bukom - Supply of labour material and equipment for HDT5/6 fin-fan area	Supply of labour, material and equipment
23	Singapore Changi Airport	Demolition - Coring to manholes
24	A&A works to Chen Su Lan Methodist Children's Home AT 202 Serangoon Garden Way	Post Tensioning Works
25	Repair to Defective Column at V8301 (2nd Level) and Concrete Support at E8524 (A&B), CD 5 at Shell Bukom	Prepacked Grouting
26	Controlled Demolition at Catholic High School	Coring of 150mm & 100mm dia. holes thru hollow core slabs for Phase 4, Blocks PD & PE
27	Catholic High School	Supply of 15.24mm dia prestressing strands
28	Shell Bukom - Pump Stut Area CD5	Prepacked Grouting
29	Controlled Demolition at Catholic High School	Cutting of RC columns for Phase 4, Blocks PB & PC
30	Shell Bukom - LOC Area	Prepacked Grouting
31	Shell Bukom - CD 5 Complex	Prepacked Grouting
32	Install bouldering wall at NACLI - South Bouna Vista Road	Supply & install wall
33	Proposed Redevelopment of Changi Prison Cluster B Complexat Upper Changi Road/Changi North Way	Post Tensioning
34	Visual inspection at Geylang VTC	Visual inspection
35	Install expansion joints at parapet wall & floor slab at Pulau Ubin	Supply materials and install new 7m of expansion joint at parapet wall & floor slab including of removal of existing worn-off expansion joint

expansion joint

<u>S/N</u>	PROJECTS PROJECTS	DESCRIPTION OF WORKS
36	Catholic High School - Wall Coring at Armoury Room	Wall Coring at Armoury Room
37	Proposed Addition and alteration to the existing factory on lot 4757(Plot A13845)MK5 at No.231A Pandan Loop	Post Tensioning Work
38	Singapore Changi Airport, T3 Level B2	Coring of 100mm dia, holes and plate bonding to post-tensioned beams
39	Lor Ah Soo (LUP Project) - Lift Motor Room	Prepacked Grouting to Existing Beams
40	No. 87 Jln Angin Laut	Repair to Water Leakage at Landscaping Pond by Cementitious Grouting with Waterproofing Membrane
41	Catholic High School	Cutting of Roof Slab & Wall Coring
42	Malaysian High Commission - Repair to Spalling and Damaged Concrete Areas at Existing Structures	Repair to Spalling and Damaged Concrete Areas at Existing Structures
43	Pavilon Park -Bukit Batok Phase 1 Repir to Water Seepage by PU Grouting	Repair to water seepgae by PU Grouting
44	Widening of Commonwealth Drive and Tanglin Halt Rd/Construction of outlet drain at Commonwealth Drive and Tanglin Halt Rd	Civil Engineering Works
45	Repair works for water seepage at Basement 2 of Merchant Court Hotel.	Concrete Repair
46	Catholic High School - Cutting of 1 window opening	Cutting of 1 window opening (1.4m x 2.1m)
47	Proposed propping detail to carry out the RC structural repair work for 4th level cantilever walkway at CD5 at Shell Pulau Bukom	Repair work
48	Parliament House	Painting to Gantry System
	Year 2003	
1	Jurong Shipyard	Repair Works to Deck 1 & 2
2	Ngee Ann Polytechnic	Design & Build Extension to Fabric Roof at Block 1
3	Villa De Este	Structural Investigation and Repairs to Fire Damage to Unit 02-109A
4	Wisma Atria	Controlled Demolition & Reanchoring Works
5	Catholic High School	Controlled Demolition to Existing Column & Wall

Parliament House

Construction of External Canopy Structures

S/N	PROJECTS PROJECTS	DESCRIPTION OF WORKS
7	Seagate Technology International, Woodlands Ave 7	Post Tensioning Works
8	Shell Eastern Petroleum @ Pulau Bukom	Repair Works to Columns & Vessel Support
	Year 2002	
1	Tampines Mall	Demolition & Strengthening Works
2	HDB Contract	Installation of Barricades, Vehicular Impact Guardrails & Planting of Shrubs at Surface Car parks
3	Singapore Changi Airport – Terminal 1	Replacement of Existing Staircases to Escalators at The Transit Lounge
4	30 Boon Lay Cougar Logistics Warehouse	Site Investigation & Strengthening Works
5	Geylang East Ave 2 Temple	Prestressing Works
6	Shell Eastern Petrolleum @ Pulau Bukom	Repair Works to Columns & Vessel Support
	Year 2001	
1	35 Robinson Road	Controlled Demolition Works
2	Plaza Singapura	Forming & Strengthening Works
3	Islamic School, Sims Avenue	Construction of new roof / Strengthening of Beams
4	Punggol East HDB Carpark	Post Tensioning to Multi Storey Carparks
5	4 Storey Factory at Pioneer Sector 2	Post Tensioning Works
6	5 Storey Single User Factory at Penjuru Close	Post Tensioning to Beam & Slab
7	Shell Eastern Petrolleum @ Pulau Bukom	Repair Works to Columns & Vessel Support
	Year 2000	
1	Jurong Point Phase II	Controlled Demolition Works
2	Singapore Tourism Board	Repainting Works with Rope Access
3	National Park Board – MacRitchie Nature Reserve	Construction of Boardwalks
4	Aspen Heights Condominium	Repair of Construction Joints & Leakage by Epoxy Grouting
5	Shell Eastern Petrolleum @ Pulau Bukom	Repair Works to Columns & Vessel Support

S/N PROJECTS

DESCRIPTION OF WORKS

Year 1997

1	Formwell Factory	Post tensioning
2	Factory for Ryobi Kiso	Post tensioning
3	Ubi Road/Ubi Avenue	Post tensioning
4	PIE / TPE Interchange	Bridge Bearings
5	Esplanade at Raffles Avenue	Structural grouting
6	St. Patrick School	Micropiles
7	Kentish Green Condominium	Jet Grouting
8	Mobil Refinery	Structural maintenance
9	Chemical Warehouse at Tuas Avenue	Post tensioning

Year 1996

1	Budget Hotel at Queen Street	Structural strengthening for retrofitting programme
2	4 storey factory at Woodlands	Post tensioning
3	Building at Kampong Ampat	Post tensioning
4	Hok Kee House	Structural retrofitting
5	Transware Distribution Services	Post tensioning
6	Seletar East Camp	Structural works
7	Esso Refinery	Structural maintenance
8	Seletar Expressway - Nee Soon Camp to Upper Thomson Road	Supply and install Bridge Bearings

Year 1995

- 1 Tampines Mall
- 2 Shell Tower
- 3 Ellery Street in Fiji
- 4 Tuas Technology Park
- 5 Oriental Hotel
- 6 Hong Leong Centre
- 7 Pulau Seraya Power Station
- 8 Celcon Building at Tannery Road / Macpherson Road

S/N PROJECTS

9 Asahi Glass Factory

Year 1994

- 1 Seletar East Camp
- 2 Seletar Expressway / Woodlands South Interchange
- 3 Sungei Api-api Bridge
- 4 Tras Street
- 5 Grangeford Apartments
- 6 Outward Bound School (Camp 2)
- 7 Bridge at Pulau Bintan
- 8 Funan Centre
- 9 Grange Road Condominium
- 10 Eastern General Hospital

Year 1993

- 1 Fowseng Plastics Factory
- 2 Shell Eastern Petroleum
- 3 Murnane Reservoir
- 4 Australian High Commission
- 5 Regent Hotel
- 6 89, Neil Road
- 7 Neptune Court
- 8 Kong Meng San Temple
- 9 Building at Robinson Road / Boon Tat Street

Year 1992

- 1 Mobil sulphur stack
- 2 Orchard Point
- 3 Yishun Multiplex Cinema
- 4 Phoenix Tower
- 5 Factory at Toh Guan Road

S/N PROJECTS

- 6 Holland Hill Mansion
- 7 Kovan Centre
- 8 Marco Polo Hotel
- 9 Raffles Hotel

Year 1991

- 1 HDB Zone B (Bishan)
- 2 Sembawang Camp
- 3 Asia Radio Building
- 4 Scotts Building
- 5 Pulau Seraya Power Station
- 6 Singapore Port Institute Building at the Port of Singapore Authority

Year 1990

- 1 Royal Holiday Inn
- 2 Shell Tower
- 3 Post Office Savings Bank Headquarters
- 4 Ocean Tower
- 5 Esso Refinery
- 6 King's Hotel
- 7 Jurong Pier Road Interchange
- 8 Balestier Road Building
- 9 Mobil Berth 2,4 and 5